


Troubleshooting Bissell Little Green BS-1720F

CONTENTS PAGE


Consumer states unit will not spray	Page 2
Consumer states unit has low/no suction	Page 4
Consumer states unit leaks above the collection tank	Page 6
Consumer states unit is leaking out the bottom	Page 7
Consumer states unit is very noisy	Page 8

Consumer states unit will not spray

Solution 1:




Solution 2:




Consumer states unit has low/no suction

Solution 1:




Solution 2:




Consumer states unit leaks above the collection tank

Solution1:




Solution 2:




Consumer states unit is leaking out the bottom

Solution 1:



Solution 2:



Consumer states **unit is very noisy**

Solution 1:

This is quite normal as the unit requires a lot of power to get deep down and extract all the deeply embedded dirt out of your carpet.